

BUILDING SAFETY CERTIFICATENo. 392/AE II/ 14/07/2026Dated: 14/07/26

It is certified that the existing building **Sunbeam School Sarnath** (name of the building or premises) at Plot No. 198, Near Ashapur Overbridge Chauraha, Beside Ramleela Maidan, Varanasi, Uttar Pradesh, PIN-221007 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school:	Block (1)	Block (2)	Block (3)	Block (4)
No. of Floor(s) in the Block:	G+3+1 Tin shed	1	1	

The building is owned/occupied by **Sunbeam School Sarnath** (name of the Institution) and has complied with the Building Safety requirements in accordance with National Building Code Rules. The building was verified by the officers concerned of Prov. Div., PWD, Varanasi Uttar Pradesh (Name of Department/Govt.) **Mr. A.M Pandey, Junior Engineer** on 10-7-2026 (date of inspection) in the presence of **Mr. Saurabh Kumar Singh, Manger Correspondent, Sunbeam School Sarnath, Plot No. 198, Near Ashapur Overbridge Chauraha, Beside Ramleela Maidan, Varanasi, Uttar Pradesh, PIN-221007** (name and address of the Manager/Secretary or his representative).

The building/premises is fit for occupancy for running school with effect from 14-07-26 for a period of 3YEAR years in accordance with rules and subject to compliance of the specific conditions as appended.

1. The school building must undergo regular inspection to ensure its upkeep.
2. Regular maintenance of the school building must be ensured.
3. _____

Issued on 14-07-2026 at Varanasi by

* Strike out whichever is not applicable. In case of block is more than six, use separate sheet for detail.

सहायक अभियन्ता
प्रांतीय खण्ड लो० नि० विभाग
Awp. - दाराप्रासी
Signature with Seal: _____
Name: **Mr. Monu Kumar Nayak**
Designation: **Assistant Engineer.**
Prov. Div., PWD, Varanasi, U.P.
(Name & Address of Department/Office)

Note: This Certificate should be signed/issued by Assistant Engineer & above officer of concerned Govt. Department only

